

X5105_FW_V1_0_06_build002_beta02 Update Description

Firmware update instructions

1. Fixed a bug in SPLT exception in CW mode of X5105_FW_V1_0_06_build001_beta08 version;
 2. Reconfigure the audio baseband unit to enhance the sense of hearing;
-

Precautions:

1. After finishing the firmware of this version, please initialize it according to the previous method;
 2. After the initialization is completed, enter the system menu and perform the reset operation;
 3. After the reset is completed, calibrate the S table as shown below:
-

For the S table calibration method, see the document "X5105 New Firmware S Table Calibration Method CZ-180901".