

X5105_FW_V1_0_04_build019 Release Notes

Note: After the firmware update is complete, you must complete the following:

1. You must follow the tutorial to initialize;
2. Please follow the tutorial to calibrate the S table;
3. Please enter the system menu to reset the system.

Improvement project:

1. Upgraded the driver of the encoder, optimized encoder response, greatly reducing the probability of lost steps and staggered steps.
2. Added an "LCD Contrast" adjustment option to the system menu. The default value is 30, and the adjustment range is 0~40.

The contrast can be adjusted according to the visual effect.